


A field assessment of the ability of Ground Penetrating Radar to detect fractures in very low permeable crystalline rock


Justine MOLRON^{1,4}, **Niklas LINDE**², **Ludovic BARON**², **Jan-Olof SELROOS**³, **Caroline DARCEL**¹ and **Philippe DAVY**⁴

¹ Itasca Consultants SAS, Ecully, France (j.molron@itasca.fr); ² Université de Lausanne, UNIL, Lausanne, Switzerland; ³ Svensk Kärnbränslehantering AB, SKB, Solna, Sweden; ⁴ Géosciences Rennes, OSUR, CNRS, Université de Rennes 1, Rennes, France


1. Methodology



2. Assessment of GPR results



3. Conclusions



Bibliography

Ericsson, L., Vidstrand, P., Christiansson, R., & Morosini, M. (2018). Comparison between blasting and wire sawing regarding hydraulic properties of the excavated damaged zone in a tunnel—Experiences from crystalline rock at the Äspö Hard Rock Laboratory, Sweden. Paper presented at the 52nd US Rock Mechanics/Geomechanics Symposium.

Mauldon, M., & Mauldon, J. G. (1997). Fracture sampling on a cylinder: From scanlines to boreholes and tunnels. *Rock Mechanics and Rock Engineering*, 30(3), 129-144.

Molron, J., Linde, N., Baron, L., Selroos, J.-O., Darcel, C. and Davy, P. (submitted). Which fractures are imaged with Ground Penetrating Radar? Results from an experiment in the Äspö Hardrock Laboratory, Sweden. *Engineering Geology*.

Piggott, A. R. (1997). Fractal relations for the diameter and trace length of disc-shaped fractures. *Journal of Geophysical Research*, 102(18), 121-125. doi: <https://doi.org/10.1029/97JB01202>

This project has received funding from the European Union's Horizon 2020 research and innovation programme under the Marie Skłodowska-Curie Grant Agreement No 722028

ITN Enigma